




RC2 Controller Installation

Requires House Wiring Experience

Nangeroni Design is not responsible for any **injury** or **damage** sustained during Installation, including **damage to the unit** caused by incorrect connection of wires

1. **Before** installing the Roadrunner Comfort in your swamp cooler's wire junction box, **identify and label wires to Pump, Low fan, Hi fan, Hot/ACL and Ground/ACN** (use provided labels). Incorrect connection of wires can **damage controller**.

2. **Turn OFF power** to the cooler controller at your home breaker (fuse) panel. Remove existing controller if any. Install wall plate, two tabs towards bottom.




3. Connect controller wires, **hot (ACL, yellow) wire last**.

Wire Colors:


- ACL (HOT): Yellow
- ACN (GND): Green
- Fan High: Black
- Fan Low: Red
- Pump: Blue

WARNING

Connecting BLUE (pump) wire to a fan wire **WILL DAMAGE** the pump circuit when power is applied.



4. **Hook controller top tabs** (1) over wall plate catches (2). Swing body downward (3) against wall plate and snap into place.




If resistance is felt, check that tabs are **fully seated**, and wiring is **deep enough** inside switch box. **DO NOT FORCE!**

5. **Restore power** to the controller via your home's breaker panel. Refer to **Quick Start guide** to begin operation.



Sensor Battery Replacement

The sensor battery should not need replacement for at least several (if not 5+) years, but will eventually need changing. When that time comes, follow diagrams below or visit our website for instructions.



Satisfaction Guaranteed Warranty & Returns

All returns within 60 days in new, resalable condition, will be refunded in full. The controller & sensor are warranted to be free from defects for TWO full years. For any failure not due to external electrical disturbance or other external cause, Nangeroni Design will repair or replace at our discretion. Nangeroni Design is not responsible for any damages beyond the unit itself due to any cause, including incorrect installation, improper usage, house wiring issues, or defects in the evaporative cooler being controlled.

More information: www.RoadrunnerComfort.com



Contact:

Email: info@RoadrunnerComfort.com

Text/Voice: 978-578-6298

Made in Los Ranchos, New Mexico
by Nangeroni Design LLC